

## SOLUTIONS TO STATIC PROBLEMS

If the material is not in web form but is sheets or magazines on a conveyor it is not possible to have a bar underneath the material.

This lower Bar is replaced by 2 x upright bars forming a goal post. The upright bars are always the opposite polarity to the horizontal bar above the material.

